

0002

**SURFACE INSPECTION
COMPLIANCE REPORT**Date of Inspection: March 7, 2001Case Serial No.: UTU-075888Operator: Resource Design Solution (Joe Dunlop)Project Description: Mining GraniteLegal Description: SE¼ Sec 35, T. 12 S., R. 7 W.Field Office: FillmoreInspector: Larry Garahana**REPORT NARRATIVE (REFERENCE STIPULATIONS BY NUMBER OR TITLE)**

The last inspection on this site was on January 10, 2001, and I was accompanied by Tom Munson of DOGM. At that inspection it was noted there had been no reclamation conducted, but there had been further work in their quarry area.

This inspection found there was a feeble attempt at reclamation (see photo). It appears they had a small piece of equipment (possibly a bobcat) on site trying to do reclamation. At best, they have completed less than five percent of the required reclamation.

I called Tom Munson from the site and discussed the situation with him, and he said he would need to schedule a date to visit the site and we could then decide what action we may need to take.

It appears they won't have the reclamation complete by the extended date (March 9, 2001), and I think we may need to take this to the next level, maybe a Notice of noncompliance.

Signature of Inspector

Signature of Authorized Officer

- 0002

Surface Inspection Compliance Report

Date of Inspection: February 28, 2001

Case Serial No.: UTU-075888
Operator: Resource Design Solutions, Inc., Joe Dunlop
Project Description: Granite
Legal Description: T. 12 S., R. 07 W., SLM. Section 35
Field Office: Fillmore Field Office
Inspector: J. Mansfield, L. Garahana

Report Narrative (Reference Stipulations by Number or Title):

The operator was met on site. The operation has expanded beyond their notice to above five acres of disturbance. The operator has been instructed to reclaim to a level of below five acres of disturbance. When we arrived the operator was waiting for his equipment to arrive. We explained to the operator again what was expected. A follow-up inspection of the operation will be made next week to insure reclamation has or is being completed.

Signature of Inspector

Signature of Authorized Officer